
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/27/2009
Test to be performed:  Ground Condition:  Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S04A 002MH	Test ID: <u>D1032-019009</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S04A002MH
5.099999905			Dye Test Visible	@ IR, 2gpm
10			Dye Test Visible	@ IR, 0.5gpm
14.80000019			Abandoned Survey	NO MORE DYE VISIBLE